

E-Zee Weblon No Show Fusible

~ A Medium Weight Backing Finisher with a Heat-Activated Adhesive

E-Zee Weblon No Show Fusible 1.65 oz

. is a low profile, soft and sheer Cut Away stabilizer with a heat-activated adhesive on one side. It is ideal as a backing finisher that is applied to the back side of finished embroidery to achieve a soft and smooth feel against the skin.

How to use Backing Finishers

1. The heat activated side of **E-Zee No Show Fusible 1.65 oz.** has shiny dots visible when looking at different angles.
2. After embroidering your design, turn the garment inside out to expose the back side.
3. Lay a piece of E-Zee No Show Fusible 1.65 oz. over the back side of the design with the rough side down.
4. Trace a trim line about $\frac{1}{2}$ " to $\frac{3}{4}$ " larger than the finished embroidery. Be sure to round the corners and cut out.
5. Place the piece over the design evenly with the shiny dot side of E-Zee No Show Fusible 1.65 oz. facing down.
6. Fuse on by applying heat at 250° to 260° for approximately 10 to 20 seconds.



Available in these sizes:

Pre-cuts

- 8" x 8" - 100 pieces per pack

Rolls

- 20" x 25 yards

Available in white and black
Item Prefix 304-(products)

Please Note

Allow time for testing with the temperatures and time guidelines for best results.

800-225-3001

madeirausa.com

E-Zee
BACKING & TOPPING®
a division of
MADEIRAUSA